

| Kaydon P/N | Timken P/N  | Consult Timken Engineering |
|------------|-------------|----------------------------|
| KA042AD4   | C68-76MC5   |                            |
| KA045AD4   | C72-80MC5   |                            |
| KA047AD4   | C76-84MC5   |                            |
| KA050AD4   | C80-88MC5   |                            |
| KA055AD4   | C88-96MC5   |                            |
| KA060AD4   | C96-104MC5  |                            |
| KA065AD4   | C104-112MC5 |                            |
| KA070AD4   | C112-120MC5 |                            |
| KA075AD4   | C120-128MC5 |                            |
| KA080AD4   | C128-136MC5 |                            |
| KA090AD4   | C144-152MC5 |                            |
| KA100AD4   | C160-168MC5 |                            |
| KA110AD4   | C176-184MC5 |                            |
| KA042AD6   | C68-76MC7   |                            |
| KA045AD6   | C72-80MC7   |                            |
| KA047AD6   | C76-84MC7   |                            |
| KA050AD6   | C80-88MC7   |                            |
| KA055AD6   | C88-96MC7   |                            |
| KA060AD6   | C96-104MC7  |                            |
| KA065AD6   | C104-112MC7 |                            |
| KA070AD6   | C112-120MC7 |                            |
| KA075AD6   | C120-128MC7 |                            |
| KA080AD6   | C128-136MC7 |                            |
| KA090AD6   | C144-152MC7 |                            |
| KA100AD6   | C160-168MC7 |                            |
| KA110AD6   | C176-184MC7 |                            |
| KA042AH4   | C68-76M5    |                            |
| KA045AH4   | C72-80M5    |                            |
| KA047AH4   | C76-84M5    |                            |
| KA050AH4   | C80-88M5    |                            |
| KA055AH4   | C88-96M5    |                            |
| KA060AH4   | C96-104M5   |                            |
| KA065AH4   | C104-112M5  |                            |
| KA070AH4   | C112-120M5  |                            |
| KA075AH4   | C120-128M5  |                            |
| KA080AH4   | C128-136M5  |                            |
| KA090AH4   | C144-152M5  |                            |
| KA100AH4   | C160-168M5  |                            |
| KA110AH4   | C176-184M5  |                            |
| KA042AH6   | C68-76M7    |                            |
| KA045AH6   | C72-80M7    |                            |
| KA047AH6   | C76-84M7    |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| KA050AH6   | C80-88M7     |
| KA055AH6   | C88-96M7     |
| KA060AH6   | C96-104M7    |
| KA065AH6   | C104-112M7   |
| KA070AH6   | C112-120M7   |
| KA075AH6   | C120-128M7   |
| KA080AH6   | C128-136M7   |
| KA090AH6   | C144-152M7   |
| KA100AH6   | C160-168M7   |
| KA110AH6   | C176-184M7   |
| KA042AZ4   | C68-76MSO5   |
| KA045AZ4   | C72-80MSO5   |
| KA047AZ4   | C76-84MSO5   |
| KA050AZ4   | C80-88MSO5   |
| KA055AZ4   | C88-96MSO5   |
| KA060AZ4   | C96-104MSO5  |
| KA065AZ4   | C104-112MSO5 |
| KA070AZ4   | C112-120MSO5 |
| KA075AZ4   | C120-128MSO5 |
| KA080AZ4   | C128-136MSO5 |
| KA090AZ4   | C144-152MSO5 |
| KA100AZ4   | C160-168MSO5 |
| KA110AZ4   | C176-184MSO5 |
| KA042AZ6   | C68-76MSO7   |
| KA045AZ6   | C72-80MSO7   |
| KA047AZ6   | C76-84MSO7   |
| KA050AZ6   | C80-88MSO7   |
| KA055AZ6   | C88-96MSO7   |
| KA060AZ6   | C96-104MSO7  |
| KA065AZ6   | C104-112MSO7 |
| KA070AZ6   | C112-120MSO7 |
| KA075AZ6   | C120-128MSO7 |
| KA080AZ6   | C128-136MSO7 |
| KA090AZ6   | C144-152MSO7 |
| KA100AZ6   | C160-168MSO7 |
| KA110AZ6   | C176-184MSO7 |
| KA042CD4   | C68-76MC5    |
| KA045CD4   | C72-80MC5    |
| KA047CD4   | C76-84MC5    |
| KA050CD4   | C80-88MC5    |
| KA055CD4   | C88-96MC5    |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KA060CD4   | C96-104MC5  |
| KA065CD4   | C104-112MC5 |
| KA070CD4   | C112-120MC5 |
| KA075CD4   | C120-128MC5 |
| KA080CD4   | C128-136MC5 |
| KA090CD4   | C144-152MC5 |
| KA100CD4   | C160-168MC5 |
| KA110CD4   | C176-184MC5 |
| KA042CD6   | C68-76MC7   |
| KA045CD6   | C72-80MC7   |
| KA047CD6   | C76-84MC7   |
| KA050CD6   | C80-88MC7   |
| KA055CD6   | C88-96MC7   |
| KA060CD6   | C96-104MC7  |
| KA065CD6   | C104-112MC7 |
| KA070CD6   | C112-120MC7 |
| KA075CD6   | C120-128MC7 |
| KA080CD6   | C128-136MC7 |
| KA090CD6   | C144-152MC7 |
| KA100CD6   | C160-168MC7 |
| KA110CD6   | C176-184MC7 |
| KA042CZ4   | C68-76ST5   |
| KA045CZ4   | C72-80ST5   |
| KA047CZ4   | C76-84ST5   |
| KA050CZ4   | C80-88ST5   |
| KA055CZ4   | C88-96ST5   |
| KA060CZ4   | C96-104ST5  |
| KA065CZ4   | C104-112ST5 |
| KA070CZ4   | C112-120ST5 |
| KA075CZ4   | C120-128ST5 |
| KA080CZ4   | C128-136ST5 |
| KA090CZ4   | C144-152ST5 |
| KA100CZ4   | C160-168ST5 |
| KA110CZ4   | C176-184ST5 |
| KA042CZ6   | C68-76ST7   |
| KA045CZ6   | C72-80ST7   |
| KA047CZ6   | C76-84ST7   |
| KA050CZ6   | C80-88ST7   |
| KA055CZ6   | C88-96ST7   |
| KA060CZ6   | C96-104ST7  |
| KA065CZ6   | C104-112ST7 |
| KA070CZ6   | C112-120ST7 |
| KA075CZ6   | C120-128ST7 |
| KA080CZ6   | C128-136ST7 |
| KA090CZ6   | C144-152ST7 |
| KA100CZ6   | C160-168ST7 |
| KA110CZ6   | C176-184ST7 |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KB042AD4   | C68-78MC5   |
| KB045AD4   | C72-82MC5   |
| KB047AD4   | C76-86MC5   |
| KB050AD4   | C80-90MC5   |
| KB055AD4   | C88-98MC5   |
| KB060AD4   | C96-106MC5  |
| KB065AD4   | C104-114MC5 |
| KB070AD4   | C112-122MC5 |
| KB075AD4   | C120-130MC5 |
| KB080AD4   | C128-138MC5 |
| KB090AD4   | C144-154MC5 |
| KB100AD4   | C160-170MC5 |
| KB110AD4   | C176-186MC5 |
| KB042AD6   | C68-78MC7   |
| KB045AD6   | C72-82MC7   |
| KB047AD6   | C76-86MC7   |
| KB050AD6   | C80-90MC7   |
| KB055AD6   | C88-98MC7   |
| KB060AD6   | C96-106MC7  |
| KB065AD6   | C104-114MC7 |
| KB070AD6   | C112-122MC7 |
| KB075AD6   | C120-130MC7 |
| KB080AD6   | C128-138MC7 |
| KB090AD6   | C144-154MC7 |
| KB100AD6   | C160-170MC7 |
| KB110AD6   | C176-186MC7 |
| KB042AH4   | C68-78M5    |
| KB045AH4   | C72-82M5    |
| KB047AH4   | C76-86M5    |
| KB050AH4   | C80-90M5    |
| KB055AH4   | C88-98M5    |
| KB060AH4   | C96-106M5   |
| KB065AH4   | C104-114M5  |
| KB070AH4   | C112-122M5  |
| KB075AH4   | C120-130M5  |
| KB080AH4   | C128-138M5  |
| KB090AH4   | C144-154M5  |
| KB100AH4   | C160-170M5  |
| KB110AH4   | C176-186M5  |
| KB042AH6   | C68-78M7    |
| KB045AH6   | C72-82M7    |
| KB047AH6   | C76-86M7    |
| KB050AH6   | C80-90M7    |
| KB055AH6   | C88-98M7    |
| KB060AH6   | C96-106M7   |
| KB065AH6   | C104-114M7  |
| KB070AH6   | C112-122M7  |

Consult Timken Engineering

## Thin Section Bearings - Kaydon to Timken Interchange

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| KB075AH6   | C120-130M7   |
| KB080AH6   | C128-138M7   |
| KB090AH6   | C144-154M7   |
| KB100AH6   | C160-170M7   |
| KB110AH6   | C176-186M7   |
| KB042AZ4   | C68-78MSO5   |
| KB045AZ4   | C72-82MSO5   |
| KB047AZ4   | C76-86MSO5   |
| KB050AZ4   | C80-90MSO5   |
| KB055AZ4   | C88-98MSO5   |
| KB060AZ4   | C96-106MSO5  |
| KB065AZ4   | C104-114MSO5 |
| KB070AZ4   | C112-122MSO5 |
| KB075AZ4   | C120-130MSO5 |
| KB080AZ4   | C128-138MSO5 |
| KB090AZ4   | C144-154MSO5 |
| KB100AZ4   | C160-170MSO5 |
| KB110AZ4   | C176-186MSO5 |
| KB042AZ6   | C68-78MSO7   |
| KB045AZ6   | C72-82MSO7   |
| KB047AZ6   | C76-86MSO7   |
| KB050AZ6   | C80-90MSO7   |
| KB055AZ6   | C88-98MSO7   |
| KB060AZ6   | C96-106MSO7  |
| KB065AZ6   | C104-114MSO7 |
| KB070AZ6   | C112-122MSO7 |
| KB075AZ6   | C120-130MSO7 |
| KB080AZ6   | C128-138MSO7 |
| KB090AZ6   | C144-154MSO7 |
| KB100AZ6   | C160-170MSO7 |
| KB110AZ6   | C176-186MSO7 |
| KB042CD4   | C68-78MC5    |
| KB045CD4   | C72-82MC5    |
| KB047CD4   | C76-86MC5    |
| KB050CD4   | C80-90MC5    |
| KB055CD4   | C88-98MC5    |
| KB060CD4   | C96-106MC5   |
| KB065CD4   | C104-114MC5  |
| KB070CD4   | C112-122MC5  |
| KB075CD4   | C120-130MC5  |
| KB080CD4   | C128-138MC5  |
| KB090CD4   | C144-154MC5  |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KB100CD4   | C160-170MC5 |
| KB110CD4   | C176-186MC5 |
| KB042CD6   | C68-78MC7   |
| KB045CD6   | C72-82MC7   |
| KB047CD6   | C76-86MC7   |
| KB050CD6   | C80-90MC7   |
| KB055CD6   | C88-98MC7   |
| KB060CD6   | C96-106MC7  |
| KB065CD6   | C104-114MC7 |
| KB070CD6   | C112-122MC7 |
| KB075CD6   | C120-130MC7 |
| KB080CD6   | C128-138MC7 |
| KB090CD6   | C144-154MC7 |
| KB100CD6   | C160-170MC7 |
| KB110CD6   | C176-186MC7 |
| KB042CZ4   | C68-78ST5   |
| KB045CZ4   | C72-82ST5   |
| KB047CZ4   | C76-86ST5   |
| KB050CZ4   | C80-90ST5   |
| KB055CZ4   | C88-98ST5   |
| KB060CZ4   | C96-106ST5  |
| KB065CZ4   | C104-114ST5 |
| KB070CZ4   | C112-122ST5 |
| KB075CZ4   | C120-130ST5 |
| KB080CZ4   | C128-138ST5 |
| KB090CZ4   | C144-154ST5 |
| KB100CZ4   | C160-170ST5 |
| KB110CZ4   | C176-186ST5 |
| KB042CZ6   | C68-78ST7   |
| KB045CZ6   | C72-82ST7   |
| KB047CZ6   | C76-86ST7   |
| KB050CZ6   | C80-90ST7   |
| KB055CZ6   | C88-98ST7   |
| KB060CZ6   | C96-106ST7  |
| KB065CZ6   | C104-114ST7 |
| KB070CZ6   | C112-122ST7 |
| KB075CZ6   | C120-130ST7 |
| KB080CZ6   | C128-138ST7 |
| KB090CZ6   | C144-154ST7 |
| KB100CZ6   | C160-170ST7 |
| KB110CZ6   | C176-186ST7 |

| Kaydon P/N | Timken P/N  | Consult Timken Engineering |
|------------|-------------|----------------------------|
| KC042AD4   | C68-80MC5   |                            |
| KC045AD4   | C72-84MC5   |                            |
| KC047AD4   | C76-88MC5   |                            |
| KC050AD4   | C80-92MC5   |                            |
| KC055AD4   | C88-100MC5  |                            |
| KC060AD4   | C96-108MC5  |                            |
| KC065AD4   | C104-116MC5 |                            |
| KC070AD4   | C112-124MC5 |                            |
| KC075AD4   | C120-132MC5 |                            |
| KC080AD4   | C128-140MC5 |                            |
| KC090AD4   | C144-156MC5 |                            |
| KC100AD4   | C160-172MC5 |                            |
| KC110AD4   | C176-188MC5 |                            |
| KC042AD6   | C68-80MC7   |                            |
| KC045AD6   | C72-84MC7   |                            |
| KC047AD6   | C76-88MC7   |                            |
| KC050AD6   | C80-92MC7   |                            |
| KC055AD6   | C88-100MC7  |                            |
| KC060AD6   | C96-108MC7  |                            |
| KC065AD6   | C104-116MC7 |                            |
| KC070AD6   | C112-124MC7 |                            |
| KC075AD6   | C120-132MC7 |                            |
| KC080AD6   | C128-140MC7 |                            |
| KC090AD6   | C144-156MC7 |                            |
| KC100AD6   | C160-172MC7 |                            |
| KC110AD6   | C176-188MC7 |                            |
| KC042AH4   | C68-80M5    |                            |
| KC045AH4   | C72-84M5    |                            |
| KC047AH4   | C76-88M5    |                            |
| KC050AH4   | C80-92M5    |                            |
| KC055AH4   | C88-100M5   |                            |
| KC060AH4   | C96-108M5   |                            |
| KC065AH4   | C104-116M5  |                            |
| KC070AH4   | C112-124M5  |                            |
| KC075AH4   | C120-132M5  |                            |
| KC080AH4   | C128-140M5  |                            |
| KC090AH4   | C144-156M5  |                            |
| KC100AH4   | C160-172M5  |                            |
| KC110AH4   | C176-188M5  |                            |
| KC042AH6   | C68-80M7    |                            |
| KC045AH6   | C72-84M7    |                            |
| KC047AH6   | C76-88M7    |                            |
| KC050AH6   | C80-92M7    |                            |
| KC055AH6   | C88-100M7   |                            |
| KC060AH6   | C96-108M7   |                            |
| KC065AH6   | C104-116M7  |                            |
| KC070AH6   | C112-124M7  |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| KC075AH6   | C120-132M7   |
| KC080AH6   | C128-140M7   |
| KC090AH6   | C144-156M7   |
| KC100AH6   | C160-172M7   |
| KC110AH6   | C176-188M7   |
| KC042AZ4   | C68-80MSO5   |
| KC045AZ4   | C72-84MSO5   |
| KC047AZ4   | C76-88MSO5   |
| KC050AZ4   | C80-92MSO5   |
| KC055AZ4   | C88-100MSO5  |
| KC060AZ4   | C96-108MSO5  |
| KC065AZ4   | C104-116MSO5 |
| KC070AZ4   | C112-124MSO5 |
| KC075AZ4   | C120-132MSO5 |
| KC080AZ4   | C128-140MSO5 |
| KC090AZ4   | C144-156MSO5 |
| KC100AZ4   | C160-172MSO5 |
| KC110AZ4   | C176-188MSO5 |
| KC042AZ6   | C68-80MSO7   |
| KC045AZ6   | C72-84MSO7   |
| KC047AZ6   | C76-88MSO7   |
| KC050AZ6   | C80-92MSO7   |
| KC055AZ6   | C88-100MSO7  |
| KC060AZ6   | C96-108MSO7  |
| KC065AZ6   | C104-116MSO7 |
| KC070AZ6   | C112-124MSO7 |
| KC075AZ6   | C120-132MSO7 |
| KC080AZ6   | C128-140MSO7 |
| KC090AZ6   | C144-156MSO7 |
| KC100AZ6   | C160-172MSO7 |
| KC110AZ6   | C176-188MSO7 |
| KC042CD4   | C68-80MC5    |
| KC045CD4   | C72-84MC5    |
| KC047CD4   | C76-88MC5    |
| KC050CD4   | C80-92MC5    |
| KC055CD4   | C88-100MC5   |
| KC060CD4   | C96-108MC5   |
| KC065CD4   | C104-116MC5  |
| KC070CD4   | C112-124MC5  |
| KC075CD4   | C120-132MC5  |
| KC080CD4   | C128-140MC5  |
| KC090CD4   | C144-156MC5  |
| KC100CD4   | C160-172MC5  |
| KC110CD4   | C176-188MC5  |
| KC042CD6   | C68-80MC7    |
| KC045CD6   | C72-84MC7    |
| KC047CD6   | C76-88MC7    |

## Thin Section Bearings - Kaydon to Timken Interchange

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KC050CD6   | C80-92MC7   |
| KC055CD6   | C88-100MC7  |
| KC060CD6   | C96-108MC7  |
| KC065CD6   | C104-116MC7 |
| KC070CD6   | C112-124MC7 |
| KC075CD6   | C120-132MC7 |
| KC080CD6   | C128-140MC7 |
| KC090CD6   | C144-156MC7 |
| KC100CD6   | C160-172MC7 |
| KC110CD6   | C176-188MC7 |
| KC042CZ4   | C68-80ST5   |
| KC045CZ4   | C72-84ST5   |
| KC047CZ4   | C76-88ST5   |
| KC050CZ4   | C80-92ST5   |
| KC055CZ4   | C88-100ST5  |
| KC060CZ4   | C96-108ST5  |
| KC065CZ4   | C104-116ST5 |
| KC070CZ4   | C112-124ST5 |
| KC075CZ4   | C120-132ST5 |
| KC080CZ4   | C128-140ST5 |
| KC090CZ4   | C144-156ST5 |
| KC100CZ4   | C160-172ST5 |
| KC110CZ4   | C176-188ST5 |
| KC042CZ6   | C68-80ST7   |
| KC045CZ6   | C72-84ST7   |
| KC047CZ6   | C76-88ST7   |
| KC050CZ6   | C80-92ST7   |
| KC055CZ6   | C88-100ST7  |
| KC060CZ6   | C96-108ST7  |
| KC065CZ6   | C104-116ST7 |
| KC070CZ6   | C112-124ST7 |
| KC075CZ6   | C120-132ST7 |
| KC080CZ6   | C128-140ST7 |
| KC090CZ6   | C144-156ST7 |
| KC100CZ6   | C160-172ST7 |
| KC110CZ6   | C176-188ST7 |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KD040AD4   | C64-80MC5   |
| KD042AD4   | C68-84MC5   |
| KD045AD4   | C72-88MC5   |
| KD047AD4   | C76-92MC5   |
| KD050AD4   | C80-96MC5   |
| KD055AD4   | C88-104MC5  |
| KD060AD4   | C96-112MC5  |
| KD065AD4   | C104-120MC5 |
| KD070AD4   | C112-128MC5 |
| KD075AD4   | C120-136MC5 |
| KD080AD4   | C128-144MC5 |
| KD090AD4   | C144-160MC5 |
| KD100AD4   | C160-176MC5 |
| KD110AD4   | C176-192MC5 |
| KD040AD6   | C64-80MC7   |
| KD042AD6   | C68-84MC7   |
| KD045AD6   | C72-88MC7   |
| KD047AD6   | C76-92MC7   |
| KD050AD6   | C80-96MC7   |
| KD055AD6   | C88-104MC7  |
| KD060AD6   | C96-112MC7  |
| KD065AD6   | C104-120MC7 |
| KD070AD6   | C112-128MC7 |
| KD075AD6   | C120-136MC7 |
| KD080AD6   | C128-144MC7 |
| KD090AD6   | C144-160MC7 |
| KD100AD6   | C160-176MC7 |
| KD110AD6   | C176-192MC7 |
| KD040AH4   | C64-80M5    |
| KD042AH4   | C68-84M5    |
| KD045AH4   | C72-88M5    |
| KD047AH4   | C76-92M5    |
| KD050AH4   | C80-96M5    |
| KD055AH4   | C88-104M5   |
| KD060AH4   | C96-112M5   |
| KD065AH4   | C104-120M5  |
| KD070AH4   | C112-128M5  |
| KD075AH4   | C120-136M5  |
| KD080AH4   | C128-144M5  |
| KD090AH4   | C144-160M5  |
| KD100AH4   | C160-176M5  |
| KD110AH4   | C176-192M5  |
| KD040AH6   | C64-80M7    |
| KD042AH6   | C68-84M7    |
| KD045AH6   | C72-88M7    |
| KD047AH6   | C76-92M7    |
| KD050AH6   | C80-96M7    |
| KD055AH6   | C88-104M7   |

Consult Timken Engineering

## Thin Section Bearings - Kaydon to Timken Interchange

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| KD060AH6   | C96-112M7    |
| KD065AH6   | C104-120M7   |
| KD070AH6   | C112-128M7   |
| KD075AH6   | C120-136M7   |
| KD080AH6   | C128-144M7   |
| KD090AH6   | C144-160M7   |
| KD100AH6   | C160-176M7   |
| KD110AH6   | C176-192M7   |
| KD040AZ4   | C64-80MSO5   |
| KD042AZ4   | C68-84MSO5   |
| KD045AZ4   | C72-88MSO5   |
| KD047AZ4   | C76-92MSO5   |
| KD050AZ4   | C80-96MSO5   |
| KD055AZ4   | C88-104MSO5  |
| KD060AZ4   | C96-112MSO5  |
| KD065AZ4   | C104-120MSO5 |
| KD070AZ4   | C112-128MSO5 |
| KD075AZ4   | C120-136MSO5 |
| KD080AZ4   | C128-144MSO5 |
| KD090AZ4   | C144-160MSO5 |
| KD100AZ4   | C160-176MSO5 |
| KD110AZ4   | C176-192MSO5 |
| KD040AZ6   | C64-80MSO7   |
| KD042AZ6   | C68-84MSO7   |
| KD045AZ6   | C72-88MSO7   |
| KD047AZ6   | C76-92MSO7   |
| KD050AZ6   | C80-96MSO7   |
| KD055AZ6   | C88-104MSO7  |
| KD060AZ6   | C96-112MSO7  |
| KD065AZ6   | C104-120MSO7 |
| KD070AZ6   | C112-128MSO7 |
| KD075AZ6   | C120-136MSO7 |
| KD080AZ6   | C128-144MSO7 |
| KD090AZ6   | C144-160MSO7 |
| KD100AZ6   | C160-176MSO7 |
| KD110AZ6   | C176-192MSO7 |
| KD040CD4   | C64-80MC5    |
| KD042CD4   | C68-84MC5    |
| KD045CD4   | C72-88MC5    |
| KD047CD4   | C76-92MC5    |
| KD050CD4   | C80-96MC5    |
| KD055CD4   | C88-104MC5   |
| KD060CD4   | C96-112MC5   |
| KD065CD4   | C104-120MC5  |
| KD070CD4   | C112-128MC5  |
| KD075CD4   | C120-136MC5  |
| KD080CD4   | C128-144MC5  |
| KD090CD4   | C144-160MC5  |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| KD100CD4   | C160-176MC5 |
| KD110CD4   | C176-192MC5 |
| KD040CD6   | C64-80MC7   |
| KD042CD6   | C68-84MC7   |
| KD045CD6   | C72-88MC7   |
| KD047CD6   | C76-92MC7   |
| KD050CD6   | C80-96MC7   |
| KD055CD6   | C88-104MC7  |
| KD060CD6   | C96-112MC7  |
| KD065CD6   | C104-120MC7 |
| KD070CD6   | C112-128MC7 |
| KD075CD6   | C120-136MC7 |
| KD080CD6   | C128-144MC7 |
| KD090CD6   | C144-160MC7 |
| KD100CD6   | C160-176MC7 |
| KD110CD6   | C176-192MC7 |
| KD040CZ4   | C64-80ST5   |
| KD042CZ4   | C68-84ST5   |
| KD045CZ4   | C72-88ST5   |
| KD047CZ4   | C76-92ST5   |
| KD050CZ4   | C80-96ST5   |
| KD055CZ4   | C88-104ST5  |
| KD060CZ4   | C96-112ST5  |
| KD065CZ4   | C104-120ST5 |
| KD070CZ4   | C112-128ST5 |
| KD075CZ4   | C120-136ST5 |
| KD080CZ4   | C128-144ST5 |
| KD090CZ4   | C144-160ST5 |
| KD100CZ4   | C160-176ST5 |
| KD110CZ4   | C176-192ST5 |
| KD040CZ6   | C64-80ST7   |
| KD042CZ6   | C68-84ST7   |
| KD045CZ6   | C72-88ST7   |
| KD047CZ6   | C76-92ST7   |
| KD050CZ6   | C80-96ST7   |
| KD055CZ6   | C88-104ST7  |
| KD060CZ6   | C96-112ST7  |
| KD065CZ6   | C104-120ST7 |
| KD070CZ6   | C112-128ST7 |
| KD075CZ6   | C120-136ST7 |
| KD080CZ6   | C128-144ST7 |
| KD090CZ6   | C144-160ST7 |
| KD100CZ6   | C160-176ST7 |
| KD110CZ6   | C176-192ST7 |

| Kaydon P/N | Timken P/N   | Consult Timken Engineering |
|------------|--------------|----------------------------|
| KF047AD4   | C76-100MC5   |                            |
| KF050AD4   | C80-104MC5   |                            |
| KF055AD4   | C88-112MC5   |                            |
| KF060AD4   | C96-120MC5   |                            |
| KF065AD4   | C104-128MC5  |                            |
| KF070AD4   | C112-136MC5  |                            |
| KF075AD4   | C120-144MC5  |                            |
| KF080AD4   | C128-152MC5  |                            |
| KF090AD4   | C144-168MC5  |                            |
| KF100AD4   | C160-184MC5  |                            |
| KF047AD6   | C76-100MC7   |                            |
| KF050AD6   | C80-104MC7   |                            |
| KF055AD6   | C88-112MC7   |                            |
| KF060AD6   | C96-120MC7   |                            |
| KF065AD6   | C104-128MC7  |                            |
| KF070AD6   | C112-136MC7  |                            |
| KF075AD6   | C120-144MC7  |                            |
| KF080AD6   | C128-152MC7  |                            |
| KF090AD6   | C144-168MC7  |                            |
| KF100AD6   | C160-184MC7  |                            |
| KF047AH4   | C76-100M5    |                            |
| KF050AH4   | C80-104M5    |                            |
| KF055AH4   | C88-112M5    |                            |
| KF060AH4   | C96-120M5    |                            |
| KF065AH4   | C104-128M5   |                            |
| KF070AH4   | C112-136M5   |                            |
| KF075AH4   | C120-144M5   |                            |
| KF080AH4   | C128-152M5   |                            |
| KF090AH4   | C144-168M5   |                            |
| KF100AH4   | C160-184M5   |                            |
| KF047AH6   | C76-100M7    |                            |
| KF050AH6   | C80-104M7    |                            |
| KF055AH6   | C88-112M7    |                            |
| KF060AH6   | C96-120M7    |                            |
| KF065AH6   | C104-128M7   |                            |
| KF070AH6   | C112-136M7   |                            |
| KF075AH6   | C120-144M7   |                            |
| KF080AH6   | C128-152M7   |                            |
| KF090AH6   | C144-168M7   |                            |
| KF100AH6   | C160-184M7   |                            |
| KF047AZ4   | C76-100MSO5  |                            |
| KF050AZ4   | C80-104MSO5  |                            |
| KF055AZ4   | C88-112MSO5  |                            |
| KF060AZ4   | C96-120MSO5  |                            |
| KF065AZ4   | C104-128MSO5 |                            |
| KF070AZ4   | C112-136MSO5 |                            |
| KF075AZ4   | C120-144MSO5 |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| KF080AZ4   | C128-152MSO5 |
| KF090AZ4   | C144-168MSO5 |
| KF100AZ4   | C160-184MSO5 |
| KF047AZ6   | C76-100MSO7  |
| KF050AZ6   | C80-104MSO7  |
| KF055AZ6   | C88-112MSO7  |
| KF060AZ6   | C96-120MSO7  |
| KF065AZ6   | C104-128MSO7 |
| KF070AZ6   | C112-136MSO7 |
| KF075AZ6   | C120-144MSO7 |
| KF080AZ6   | C128-152MSO7 |
| KF090AZ6   | C144-168MSO7 |
| KF100AZ6   | C160-184MSO7 |
| KF047CD4   | C76-100MC5   |
| KF050CD4   | C80-104MC5   |
| KF055CD4   | C88-112MC5   |
| KF060CD4   | C96-120MC5   |
| KF065CD4   | C104-128MC5  |
| KF070CD4   | C112-136MC5  |
| KF075CD4   | C120-144MC5  |
| KF080CD4   | C128-152MC5  |
| KF090CD4   | C144-168MC5  |
| KF100CD4   | C160-184MC5  |
| KF047CD6   | C76-100MC7   |
| KF050CD6   | C80-104MC7   |
| KF055CD6   | C88-112MC7   |
| KF060CD6   | C96-120MC7   |
| KF065CD6   | C104-128MC7  |
| KF070CD6   | C112-136MC7  |
| KF075CD6   | C120-144MC7  |
| KF080CD6   | C128-152MC7  |
| KF090CD6   | C144-168MC7  |
| KF100CD6   | C160-184MC7  |
| KF047CZ4   | C76-100ST5   |
| KF050CZ4   | C80-104ST5   |
| KF055CZ4   | C88-112ST5   |
| KF060CZ4   | C96-120ST5   |
| KF065CZ4   | C104-128ST5  |
| KF070CZ4   | C112-136ST5  |
| KF075CZ4   | C120-144ST5  |
| KF080CZ4   | C128-152ST5  |
| KF090CZ4   | C144-168ST5  |
| KF100CZ4   | C160-184ST5  |
| KF047CZ6   | C76-100ST7   |
| KF050CZ6   | C80-104ST7   |
| KF055CZ6   | C88-112ST7   |
| KF060CZ6   | C96-120ST7   |

| Kaydon P/N | Timken P/N  | Consult Timken Engineering |
|------------|-------------|----------------------------|
| KF065CZ6   | C104-128ST7 |                            |
| KF070CZ6   | C112-136ST7 |                            |
| KF075CZ6   | C120-144ST7 |                            |
| KF080CZ6   | C128-152ST7 |                            |
| KF090CZ6   | C144-168ST7 |                            |
| KF100CZ6   | C160-184ST7 |                            |
| SA042AD4   | S68-76MC5   |                            |
| SA045AD4   | S72-80MC5   |                            |
| SA047AD4   | S76-84MC5   |                            |
| SA050AD4   | S80-88MC5   |                            |
| SA055AD4   | S88-96MC5   |                            |
| SA060AD4   | S96-104MC5  |                            |
| SA065AD4   | S104-112MC5 |                            |
| SA070AD4   | S112-120MC5 |                            |
| SA075AD4   | S120-128MC5 |                            |
| SA080AD4   | S128-136MC5 |                            |
| SA090AD4   | S144-152MC5 |                            |
| SA100AD4   | S160-168MC5 |                            |
| SA110AD4   | S176-184MC5 |                            |
| SA042AD6   | S68-76MC7   |                            |
| SA045AD6   | S72-80MC7   |                            |
| SA047AD6   | S76-84MC7   |                            |
| SA050AD6   | S80-88MC7   |                            |
| SA055AD6   | S88-96MC7   |                            |
| SA060AD6   | S96-104MC7  |                            |
| SA065AD6   | S104-112MC7 |                            |
| SA070AD6   | S112-120MC7 |                            |
| SA075AD6   | S120-128MC7 |                            |
| SA080AD6   | S128-136MC7 |                            |
| SA090AD6   | S144-152MC7 |                            |
| SA100AD6   | S160-168MC7 |                            |
| SA110AD6   | S176-184MC7 |                            |
| SA042AH4   | S68-76M5    |                            |
| SA045AH4   | S72-80M5    |                            |
| SA047AH4   | S76-84M5    |                            |
| SA050AH4   | S80-88M5    |                            |
| SA055AH4   | S88-96M5    |                            |
| SA060AH4   | S96-104M5   |                            |
| SA065AH4   | S104-112M5  |                            |
| SA070AH4   | S112-120M5  |                            |
| SA075AH4   | S120-128M5  |                            |
| SA080AH4   | S128-136M5  |                            |
| SA090AH4   | S144-152M5  |                            |
| SA100AH4   | S160-168M5  |                            |
| SA110AH4   | S176-184M5  |                            |
| SA042AH6   | S68-76M7    |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| SA045AH6   | S72-80M7     |
| SA047AH6   | S76-84M7     |
| SA050AH6   | S80-88M7     |
| SA055AH6   | S88-96M7     |
| SA060AH6   | S96-104M7    |
| SA065AH6   | S104-112M7   |
| SA070AH6   | S112-120M7   |
| SA075AH6   | S120-128M7   |
| SA080AH6   | S128-136M7   |
| SA090AH6   | S144-152M7   |
| SA100AH6   | S160-168M7   |
| SA110AH6   | S176-184M7   |
| SA042AZ4   | S68-76MSO5   |
| SA045AZ4   | S72-80MSO5   |
| SA047AZ4   | S76-84MSO5   |
| SA050AZ4   | S80-88MSO5   |
| SA055AZ4   | S88-96MSO5   |
| SA060AZ4   | S96-104MSO5  |
| SA065AZ4   | S104-112MSO5 |
| SA070AZ4   | S112-120MSO5 |
| SA075AZ4   | S120-128MSO5 |
| SA080AZ4   | S128-136MSO5 |
| SA090AZ4   | S144-152MSO5 |
| SA100AZ4   | S160-168MSO5 |
| SA110AZ4   | S176-184MSO5 |
| SA042AZ6   | S68-76MSO7   |
| SA045AZ6   | S72-80MSO7   |
| SA047AZ6   | S76-84MSO7   |
| SA050AZ6   | S80-88MSO7   |
| SA055AZ6   | S88-96MSO7   |
| SA060AZ6   | S96-104MSO7  |
| SA065AZ6   | S104-112MSO7 |
| SA070AZ6   | S112-120MSO7 |
| SA075AZ6   | S120-128MSO7 |
| SA080AZ6   | S128-136MSO7 |
| SA090AZ6   | S144-152MSO7 |
| SA100AZ6   | S160-168MSO7 |
| SA110AZ6   | S176-184MSO7 |
| SA042CD4   | S68-76MC5    |
| SA045CD4   | S72-80MC5    |
| SA047CD4   | S76-84MC5    |
| SA050CD4   | S80-88MC5    |
| SA055CD4   | S88-96MC5    |
| SA060CD4   | S96-104MC5   |
| SA065CD4   | S104-112MC5  |
| SA070CD4   | S112-120MC5  |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SA075CD4   | S120-128MC5 |
| SA080CD4   | S128-136MC5 |
| SA090CD4   | S144-152MC5 |
| SA100CD4   | S160-168MC5 |
| SA110CD4   | S176-184MC5 |
| SA042CD6   | S68-76MC7   |
| SA045CD6   | S72-80MC7   |
| SA047CD6   | S76-84MC7   |
| SA050CD6   | S80-88MC7   |
| SA055CD6   | S88-96MC7   |
| SA060CD6   | S96-104MC7  |
| SA065CD6   | S104-112MC7 |
| SA070CD6   | S112-120MC7 |
| SA075CD6   | S120-128MC7 |
| SA080CD6   | S128-136MC7 |
| SA090CD6   | S144-152MC7 |
| SA100CD6   | S160-168MC7 |
| SA110CD6   | S176-184MC7 |
| SA042CZ4   | S68-76ST5   |
| SA045CZ4   | S72-80ST5   |
| SA047CZ4   | S76-84ST5   |
| SA050CZ4   | S80-88ST5   |
| SA055CZ4   | S88-96ST5   |
| SA060CZ4   | S96-104ST5  |
| SA065CZ4   | S104-112ST5 |
| SA070CZ4   | S112-120ST5 |
| SA075CZ4   | S120-128ST5 |
| SA080CZ4   | S128-136ST5 |
| SA090CZ4   | S144-152ST5 |
| SA100CZ4   | S160-168ST5 |
| SA110CZ4   | S176-184ST5 |
| SA042CZ6   | S68-76ST7   |
| SA045CZ6   | S72-80ST7   |
| SA047CZ6   | S76-84ST7   |
| SA050CZ6   | S80-88ST7   |
| SA055CZ6   | S88-96ST7   |
| SA060CZ6   | S96-104ST7  |
| SA065CZ6   | S104-112ST7 |
| SA070CZ6   | S112-120ST7 |
| SA075CZ6   | S120-128ST7 |
| SA080CZ6   | S128-136ST7 |
| SA090CZ6   | S144-152ST7 |
| SA100CZ6   | S160-168ST7 |
| SA110CZ6   | S176-184ST7 |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SB042AD4   | S68-78MC5   |
| SB045AD4   | S72-82MC5   |
| SB047AD4   | S76-86MC5   |
| SB050AD4   | S80-90MC5   |
| SB055AD4   | S88-98MC5   |
| SB060AD4   | S96-106MC5  |
| SB065AD4   | S104-114MC5 |
| SB070AD4   | S112-122MC5 |
| SB075AD4   | S120-130MC5 |
| SB080AD4   | S128-138MC5 |
| SB090AD4   | S144-154MC5 |
| SB100AD4   | S160-170MC5 |
| SB110AD4   | S176-186MC5 |
| SB042AD6   | S68-78MC7   |
| SB045AD6   | S72-82MC7   |
| SB047AD6   | S76-86MC7   |
| SB050AD6   | S80-90MC7   |
| SB055AD6   | S88-98MC7   |
| SB060AD6   | S96-106MC7  |
| SB065AD6   | S104-114MC7 |
| SB070AD6   | S112-122MC7 |
| SB075AD6   | S120-130MC7 |
| SB080AD6   | S128-138MC7 |
| SB090AD6   | S144-154MC7 |
| SB100AD6   | S160-170MC7 |
| SB110AD6   | S176-186MC7 |
| SB042AH4   | S68-78M5    |
| SB045AH4   | S72-82M5    |
| SB047AH4   | S76-86M5    |
| SB050AH4   | S80-90M5    |
| SB055AH4   | S88-98M5    |
| SB060AH4   | S96-106M5   |
| SB065AH4   | S104-114M5  |
| SB070AH4   | S112-122M5  |
| SB075AH4   | S120-130M5  |
| SB080AH4   | S128-138M5  |
| SB090AH4   | S144-154M5  |
| SB100AH4   | S160-170M5  |
| SB110AH4   | S176-186M5  |
| SB042AH6   | S68-78M7    |
| SB045AH6   | S72-82M7    |
| SB047AH6   | S76-86M7    |
| SB050AH6   | S80-90M7    |
| SB055AH6   | S88-98M7    |
| SB060AH6   | S96-106M7   |
| SB065AH6   | S104-114M7  |
| SB070AH6   | S112-122M7  |
| SB075AH6   | S120-130M7  |
|            |             |
|            |             |

Consult Timken Engineering

## Thin Section Bearings - Kaydon to Timken Interchange

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| SB080AH6   | S128-138M7   |
| SB090AH6   | S144-154M7   |
| SB100AH6   | S160-170M7   |
| SB110AH6   | S176-186M7   |
| SB042AZ4   | S68-78MSO5   |
| SB045AZ4   | S72-82MSO5   |
| SB047AZ4   | S76-86MSO5   |
| SB050AZ4   | S80-90MSO5   |
| SB055AZ4   | S88-98MSO5   |
| SB060AZ4   | S96-106MSO5  |
| SB065AZ4   | S104-114MSO5 |
| SB070AZ4   | S112-122MSO5 |
| SB075AZ4   | S120-130MSO5 |
| SB080AZ4   | S128-138MSO5 |
| SB090AZ4   | S144-154MSO5 |
| SB100AZ4   | S160-170MSO5 |
| SB110AZ4   | S176-186MSO5 |
| SB042AZ6   | S68-78MSO7   |
| SB045AZ6   | S72-82MSO7   |
| SB047AZ6   | S76-86MSO7   |
| SB050AZ6   | S80-90MSO7   |
| SB055AZ6   | S88-98MSO7   |
| SB060AZ6   | S96-106MSO7  |
| SB065AZ6   | S104-114MSO7 |
| SB070AZ6   | S112-122MSO7 |
| SB075AZ6   | S120-130MSO7 |
| SB080AZ6   | S128-138MSO7 |
| SB090AZ6   | S144-154MSO7 |
| SB100AZ6   | S160-170MSO7 |
| SB110AZ6   | S176-186MSO7 |
| SB042CD4   | S68-78MC5    |
| SB045CD4   | S72-82MC5    |
| SB047CD4   | S76-86MC5    |
| SB050CD4   | S80-90MC5    |
| SB055CD4   | S88-98MC5    |
| SB060CD4   | S96-106MC5   |
| SB065CD4   | S104-114MC5  |
| SB070CD4   | S112-122MC5  |
| SB075CD4   | S120-130MC5  |
| SB080CD4   | S128-138MC5  |
| SB090CD4   | S144-154MC5  |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SB100CD4   | S160-170MC5 |
| SB110CD4   | S176-186MC5 |
| SB042CD6   | S68-78MC7   |
| SB045CD6   | S72-82MC7   |
| SB047CD6   | S76-86MC7   |
| SB050CD6   | S80-90MC7   |
| SB055CD6   | S88-98MC7   |
| SB060CD6   | S96-106MC7  |
| SB065CD6   | S104-114MC7 |
| SB070CD6   | S112-122MC7 |
| SB075CD6   | S120-130MC7 |
| SB080CD6   | S128-138MC7 |
| SB090CD6   | S144-154MC7 |
| SB100CD6   | S160-170MC7 |
| SB110CD6   | S176-186MC7 |
| SB042CZ4   | S68-78ST5   |
| SB045CZ4   | S72-82ST5   |
| SB047CZ4   | S76-86ST5   |
| SB050CZ4   | S80-90ST5   |
| SB055CZ4   | S88-98ST5   |
| SB060CZ4   | S96-106ST5  |
| SB065CZ4   | S104-114ST5 |
| SB070CZ4   | S112-122ST5 |
| SB075CZ4   | S120-130ST5 |
| SB080CZ4   | S128-138ST5 |
| SB090CZ4   | S144-154ST5 |
| SB100CZ4   | S160-170ST5 |
| SB110CZ4   | S176-186ST5 |
| SB042CZ6   | S68-78ST7   |
| SB045CZ6   | S72-82ST7   |
| SB047CZ6   | S76-86ST7   |
| SB050CZ6   | S80-90ST7   |
| SB055CZ6   | S88-98ST7   |
| SB060CZ6   | S96-106ST7  |
| SB065CZ6   | S104-114ST7 |
| SB070CZ6   | S112-122ST7 |
| SB075CZ6   | S120-130ST7 |
| SB080CZ6   | S128-138ST7 |
| SB090CZ6   | S144-154ST7 |
| SB100CZ6   | S160-170ST7 |
| SB110CZ6   | S176-186ST7 |

| Kaydon P/N | Timken P/N  | Consult Timken Engineering |
|------------|-------------|----------------------------|
| SC042AD4   | S68-80MC5   |                            |
| SC045AD4   | S72-84MC5   |                            |
| SC047AD4   | S76-88MC5   |                            |
| SC050AD4   | S80-92MC5   |                            |
| SC055AD4   | S88-100MC5  |                            |
| SC060AD4   | S96-108MC5  |                            |
| SC065AD4   | S104-116MC5 |                            |
| SC070AD4   | S112-124MC5 |                            |
| SC075AD4   | S120-132MC5 |                            |
| SC080AD4   | S128-140MC5 |                            |
| SC090AD4   | S144-156MC5 |                            |
| SC100AD4   | S160-172MC5 |                            |
| SC110AD4   | S176-188MC5 |                            |
| SC042AD6   | S68-80MC7   |                            |
| SC045AD6   | S72-84MC7   |                            |
| SC047AD6   | S76-88MC7   |                            |
| SC050AD6   | S80-92MC7   |                            |
| SC055AD6   | S88-100MC7  |                            |
| SC060AD6   | S96-108MC7  |                            |
| SC065AD6   | S104-116MC7 |                            |
| SC070AD6   | S112-124MC7 |                            |
| SC075AD6   | S120-132MC7 |                            |
| SC080AD6   | S128-140MC7 |                            |
| SC090AD6   | S144-156MC7 |                            |
| SC100AD6   | S160-172MC7 |                            |
| SC110AD6   | S176-188MC7 |                            |
| SC042AH4   | S68-80M5    |                            |
| SC045AH4   | S72-84M5    |                            |
| SC047AH4   | S76-88M5    |                            |
| SC050AH4   | S80-92M5    |                            |
| SC055AH4   | S88-100M5   |                            |
| SC060AH4   | S96-108M5   |                            |
| SC065AH4   | S104-116M5  |                            |
| SC070AH4   | S112-124M5  |                            |
| SC075AH4   | S120-132M5  |                            |
| SC080AH4   | S128-140M5  |                            |
| SC090AH4   | S144-156M5  |                            |
| SC100AH4   | S160-172M5  |                            |
| SC110AH4   | S176-188M5  |                            |
| SC042AH6   | S68-80M7    |                            |
| SC045AH6   | S72-84M7    |                            |
| SC047AH6   | S76-88M7    |                            |
| SC050AH6   | S80-92M7    |                            |
| SC055AH6   | S88-100M7   |                            |
| SC060AH6   | S96-108M7   |                            |
| SC065AH6   | S104-116M7  |                            |
| SC070AH6   | S112-124M7  |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| SC075AH6   | S120-132M7   |
| SC080AH6   | S128-140M7   |
| SC090AH6   | S144-156M7   |
| SC100AH6   | S160-172M7   |
| SC110AH6   | S176-188M7   |
| SC042AZ4   | S68-80MSO5   |
| SC045AZ4   | S72-84MSO5   |
| SC047AZ4   | S76-88MSO5   |
| SC050AZ4   | S80-92MSO5   |
| SC055AZ4   | S88-100MSO5  |
| SC060AZ4   | S96-108MSO5  |
| SC065AZ4   | S104-116MSO5 |
| SC070AZ4   | S112-124MSO5 |
| SC075AZ4   | S120-132MSO5 |
| SC080AZ4   | S128-140MSO5 |
| SC090AZ4   | S144-156MSO5 |
| SC100AZ4   | S160-172MSO5 |
| SC110AZ4   | S176-188MSO5 |
| SC042AZ6   | S68-80MSO7   |
| SC045AZ6   | S72-84MSO7   |
| SC047AZ6   | S76-88MSO7   |
| SC050AZ6   | S80-92MSO7   |
| SC055AZ6   | S88-100MSO7  |
| SC060AZ6   | S96-108MSO7  |
| SC065AZ6   | S104-116MSO7 |
| SC070AZ6   | S112-124MSO7 |
| SC075AZ6   | S120-132MSO7 |
| SC080AZ6   | S128-140MSO7 |
| SC090AZ6   | S144-156MSO7 |
| SC100AZ6   | S160-172MSO7 |
| SC110AZ6   | S176-188MSO7 |
| SC042CD4   | S68-80MC5    |
| SC045CD4   | S72-84MC5    |
| SC047CD4   | S76-88MC5    |
| SC050CD4   | S80-92MC5    |
| SC055CD4   | S88-100MC5   |
| SC060CD4   | S96-108MC5   |
| SC065CD4   | S104-116MC5  |
| SC070CD4   | S112-124MC5  |
| SC075CD4   | S120-132MC5  |
| SC080CD4   | S128-140MC5  |
| SC090CD4   | S144-156MC5  |
| SC100CD4   | S160-172MC5  |
| SC110CD4   | S176-188MC5  |
| SC042CD6   | S68-80MC7    |
| SC045CD6   | S72-84MC7    |
| SC047CD6   | S76-88MC7    |
| SC050CD6   | S80-92MC7    |
| SC055CD6   | S88-100MC7   |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SC060CD6   | S96-108MC7  |
| SC065CD6   | S104-116MC7 |
| SC070CD6   | S112-124MC7 |
| SC075CD6   | S120-132MC7 |
| SC080CD6   | S128-140MC7 |
| SC090CD6   | S144-156MC7 |
| SC100CD6   | S160-172MC7 |
| SC110CD6   | S176-188MC7 |
| SC042CZ4   | S68-80ST5   |
| SC045CZ4   | S72-84ST5   |
| SC047CZ4   | S76-88ST5   |
| SC050CZ4   | S80-92ST5   |
| SC055CZ4   | S88-100ST5  |
| SC060CZ4   | S96-108ST5  |
| SC065CZ4   | S104-116ST5 |
| SC070CZ4   | S112-124ST5 |
| SC075CZ4   | S120-132ST5 |
| SC080CZ4   | S128-140ST5 |
| SC090CZ4   | S144-156ST5 |
| SC100CZ4   | S160-172ST5 |
| SC110CZ4   | S176-188ST5 |
| SC042CZ6   | S68-80ST7   |
| SC045CZ6   | S72-84ST7   |
| SC047CZ6   | S76-88ST7   |
| SC050CZ6   | S80-92ST7   |
| SC055CZ6   | S88-100ST7  |
| SC060CZ6   | S96-108ST7  |
| SC065CZ6   | S104-116ST7 |
| SC070CZ6   | S112-124ST7 |
| SC075CZ6   | S120-132ST7 |
| SC080CZ6   | S128-140ST7 |
| SC090CZ6   | S144-156ST7 |
| SC100CZ6   | S160-172ST7 |
| SC110CZ6   | S176-188ST7 |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SD040AD4   | S64-80MC5   |
| SD042AD4   | S68-84MC5   |
| SD045AD4   | S72-88MC5   |
| SD047AD4   | S76-92MC5   |
| SD050AD4   | S80-96MC5   |
| SD055AD4   | S88-104MC5  |
| SD060AD4   | S96-112MC5  |
| SD065AD4   | S104-120MC5 |
| SD070AD4   | S112-128MC5 |
| SD075AD4   | S120-136MC5 |
| SD080AD4   | S128-144MC5 |
| SD090AD4   | S144-160MC5 |
| SD100AD4   | S160-176MC5 |
| SD110AD4   | S176-192MC5 |
| SD040AD6   | S64-80MC7   |
| SD042AD6   | S68-84MC7   |
| SD045AD6   | S72-88MC7   |
| SD047AD6   | S76-92MC7   |
| SD050AD6   | S80-96MC7   |
| SD055AD6   | S88-104MC7  |
| SD060AD6   | S96-112MC7  |
| SD065AD6   | S104-120MC7 |
| SD070AD6   | S112-128MC7 |
| SD075AD6   | S120-136MC7 |
| SD080AD6   | S128-144MC7 |
| SD090AD6   | S144-160MC7 |
| SD100AD6   | S160-176MC7 |
| SD110AD6   | S176-192MC7 |
| SD040AH4   | S64-80M5    |
| SD042AH4   | S68-84M5    |
| SD045AH4   | S72-88M5    |
| SD047AH4   | S76-92M5    |
| SD050AH4   | S80-96M5    |
| SD055AH4   | S88-104M5   |
| SD060AH4   | S96-112M5   |
| SD065AH4   | S104-120M5  |
| SD070AH4   | S112-128M5  |
| SD075AH4   | S120-136M5  |
| SD080AH4   | S128-144M5  |
| SD090AH4   | S144-160M5  |
| SD100AH4   | S160-176M5  |
| SD110AH4   | S176-192M5  |
| SD040AH6   | S64-80M7    |
| SD042AH6   | S68-84M7    |
| SD045AH6   | S72-88M7    |
| SD047AH6   | S76-92M7    |
| SD050AH6   | S80-96M7    |

Consult Timken Engineering

## Thin Section Bearings - Kaydon to Timken Interchange

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| SD055AH6   | S88-104M7    |
| SD060AH6   | S96-112M7    |
| SD065AH6   | S104-120M7   |
| SD070AH6   | S112-128M7   |
| SD075AH6   | S120-136M7   |
| SD080AH6   | S128-144M7   |
| SD090AH6   | S144-160M7   |
| SD100AH6   | S160-176M7   |
| SD110AH6   | S176-192M7   |
| SD040AZ4   | S64-80MSO5   |
| SD042AZ4   | S68-84MSO5   |
| SD045AZ4   | S72-88MSO5   |
| SD047AZ4   | S76-92MSO5   |
| SD050AZ4   | S80-96MSO5   |
| SD055AZ4   | S88-104MSO5  |
| SD060AZ4   | S96-112MSO5  |
| SD065AZ4   | S104-120MSO5 |
| SD070AZ4   | S112-128MSO5 |
| SD075AZ4   | S120-136MSO5 |
| SD080AZ4   | S128-144MSO5 |
| SD090AZ4   | S144-160MSO5 |
| SD100AZ4   | S160-176MSO5 |
| SD110AZ4   | S176-192MSO5 |
| SD040AZ6   | S64-80MSO7   |
| SD042AZ6   | S68-84MSO7   |
| SD045AZ6   | S72-88MSO7   |
| SD047AZ6   | S76-92MSO7   |
| SD050AZ6   | S80-96MSO7   |
| SD055AZ6   | S88-104MSO7  |
| SD060AZ6   | S96-112MSO7  |
| SD065AZ6   | S104-120MSO7 |
| SD070AZ6   | S112-128MSO7 |
| SD075AZ6   | S120-136MSO7 |
| SD080AZ6   | S128-144MSO7 |
| SD090AZ6   | S144-160MSO7 |
| SD100AZ6   | S160-176MSO7 |
| SD110AZ6   | S176-192MSO7 |
| SD040CD4   | S64-80MC5    |
| SD042CD4   | S68-84MC5    |
| SD045CD4   | S72-88MC5    |
| SD047CD4   | S76-92MC5    |
| SD050CD4   | S80-96MC5    |
| SD055CD4   | S88-104MC5   |
| SD060CD4   | S96-112MC5   |
| SD065CD4   | S104-120MC5  |
| SD070CD4   | S112-128MC5  |
| SD075CD4   | S120-136MC5  |
| SD080CD4   | S128-144MC5  |
| SD090CD4   | S144-160MC5  |

| Kaydon P/N | Timken P/N  |
|------------|-------------|
| SD100CD4   | S160-176MC5 |
| SD110CD4   | S176-192MC5 |
| SD040CD6   | S64-80MC7   |
| SD042CD6   | S68-84MC7   |
| SD045CD6   | S72-88MC7   |
| SD047CD6   | S76-92MC7   |
| SD050CD6   | S80-96MC7   |
| SD055CD6   | S88-104MC7  |
| SD060CD6   | S96-112MC7  |
| SD065CD6   | S104-120MC7 |
| SD070CD6   | S112-128MC7 |
| SD075CD6   | S120-136MC7 |
| SD080CD6   | S128-144MC7 |
| SD090CD6   | S144-160MC7 |
| SD100CD6   | S160-176MC7 |
| SD110CD6   | S176-192MC7 |
| SD040CZ4   | S64-80ST5   |
| SD042CZ4   | S68-84ST5   |
| SD045CZ4   | S72-88ST5   |
| SD047CZ4   | S76-92ST5   |
| SD050CZ4   | S80-96ST5   |
| SD055CZ4   | S88-104ST5  |
| SD060CZ4   | S96-112ST5  |
| SD065CZ4   | S104-120ST5 |
| SD070CZ4   | S112-128ST5 |
| SD075CZ4   | S120-136ST5 |
| SD080CZ4   | S128-144ST5 |
| SD090CZ4   | S144-160ST5 |
| SD100CZ4   | S160-176ST5 |
| SD110CZ4   | S176-192ST5 |
| SD040CZ6   | S64-80ST7   |
| SD042CZ6   | S68-84ST7   |
| SD045CZ6   | S72-88ST7   |
| SD047CZ6   | S76-92ST7   |
| SD050CZ6   | S80-96ST7   |
| SD055CZ6   | S88-104ST7  |
| SD060CZ6   | S96-112ST7  |
| SD065CZ6   | S104-120ST7 |
| SD070CZ6   | S112-128ST7 |
| SD075CZ6   | S120-136ST7 |
| SD080CZ6   | S128-144ST7 |
| SD090CZ6   | S144-160ST7 |
| SD100CZ6   | S160-176ST7 |
| SD110CZ6   | S176-192ST7 |

| Kaydon P/N | Timken P/N   | Consult Timken Engineering |
|------------|--------------|----------------------------|
| SF047AD4   | S76-100MC5   |                            |
| SF050AD4   | S80-104MC5   |                            |
| SF055AD4   | S88-112MC5   |                            |
| SF060AD4   | S96-120MC5   |                            |
| SF065AD4   | S104-128MC5  |                            |
| SF070AD4   | S112-136MC5  |                            |
| SF075AD4   | S120-144MC5  |                            |
| SF080AD4   | S128-152MC5  |                            |
| SF090AD4   | S144-168MC5  |                            |
| SF100AD4   | S160-184MC5  |                            |
| SF047AD6   | S76-100MC7   |                            |
| SF050AD6   | S80-104MC7   |                            |
| SF055AD6   | S88-112MC7   |                            |
| SF060AD6   | S96-120MC7   |                            |
| SF065AD6   | S104-128MC7  |                            |
| SF070AD6   | S112-136MC7  |                            |
| SF075AD6   | S120-144MC7  |                            |
| SF080AD6   | S128-152MC7  |                            |
| SF090AD6   | S144-168MC7  |                            |
| SF100AD6   | S160-184MC7  |                            |
| SF047AH4   | S76-100M5    |                            |
| SF050AH4   | S80-104M5    |                            |
| SF055AH4   | S88-112M5    |                            |
| SF060AH4   | S96-120M5    |                            |
| SF065AH4   | S104-128M5   |                            |
| SF070AH4   | S112-136M5   |                            |
| SF075AH4   | S120-144M5   |                            |
| SF080AH4   | S128-152M5   |                            |
| SF090AH4   | S144-168M5   |                            |
| SF100AH4   | S160-184M5   |                            |
| SF047AH6   | S76-100M7    |                            |
| SF050AH6   | S80-104M7    |                            |
| SF055AH6   | S88-112M7    |                            |
| SF060AH6   | S96-120M7    |                            |
| SF065AH6   | S104-128M7   |                            |
| SF070AH6   | S112-136M7   |                            |
| SF075AH6   | S120-144M7   |                            |
| SF080AH6   | S128-152M7   |                            |
| SF090AH6   | S144-168M7   |                            |
| SF100AH6   | S160-184M7   |                            |
| SF047AZ4   | S76-100MSO5  |                            |
| SF050AZ4   | S80-104MSO5  |                            |
| SF055AZ4   | S88-112MSO5  |                            |
| SF060AZ4   | S96-120MSO5  |                            |
| SF065AZ4   | S104-128MSO5 |                            |
| SF070AZ4   | S112-136MSO5 |                            |
| SF075AZ4   | S120-144MSO5 |                            |
| SF080AZ4   | S128-152MSO5 |                            |
| SF090AZ4   | S144-168MSO5 |                            |
| SF100AZ4   | S160-184MSO5 |                            |

| Kaydon P/N | Timken P/N   |
|------------|--------------|
| SF047AZ6   | S76-100MSO7  |
| SF050AZ6   | S80-104MSO7  |
| SF055AZ6   | S88-112MSO7  |
| SF060AZ6   | S96-120MSO7  |
| SF065AZ6   | S104-128MSO7 |
| SF070AZ6   | S112-136MSO7 |
| SF075AZ6   | S120-144MSO7 |
| SF080AZ6   | S128-152MSO7 |
| SF090AZ6   | S144-168MSO7 |
| SF100AZ6   | S160-184MSO7 |
| SF047CD4   | S76-100MC5   |
| SF050CD4   | S80-104MC5   |
| SF055CD4   | S88-112MC5   |
| SF060CD4   | S96-120MC5   |
| SF065CD4   | S104-128MC5  |
| SF070CD4   | S112-136MC5  |
| SF075CD4   | S120-144MC5  |
| SF080CD4   | S128-152MC5  |
| SF090CD4   | S144-168MC5  |
| SF100CD4   | S160-184MC5  |
| SF047CD6   | S76-100MC7   |
| SF050CD6   | S80-104MC7   |
| SF055CD6   | S88-112MC7   |
| SF060CD6   | S96-120MC7   |
| SF065CD6   | S104-128MC7  |
| SF070CD6   | S112-136MC7  |
| SF075CD6   | S120-144MC7  |
| SF080CD6   | S128-152MC7  |
| SF090CD6   | S144-168MC7  |
| SF100CD6   | S160-184MC7  |
| SF047CZ4   | S76-100ST5   |
| SF050CZ4   | S80-104ST5   |
| SF055CZ4   | S88-112ST5   |
| SF060CZ4   | S96-120ST5   |
| SF065CZ4   | S104-128ST5  |
| SF070CZ4   | S112-136ST5  |
| SF075CZ4   | S120-144ST5  |
| SF080CZ4   | S128-152ST5  |
| SF090CZ4   | S144-168ST5  |
| SF100CZ4   | S160-184ST5  |
| SF047CZ6   | S76-100ST7   |
| SF050CZ6   | S80-104ST7   |
| SF055CZ6   | S88-112ST7   |
| SF060CZ6   | S96-120ST7   |
| SF065CZ6   | S104-128ST7  |
| SF070CZ6   | S112-136ST7  |
| SF075CZ6   | S120-144ST7  |
| SF080CZ6   | S128-152ST7  |
| SF090CZ6   | S144-168ST7  |
| SF100CZ6   | S160-184ST7  |